

SB -912 i-000R10  
SB-912-000R22  
SB-914-000R22  
SB-505-000R2  
SB-535-000R2



This SB revises SB-505-000/SB-535-000/SB-912 i-000R9,  
SB-912-000/SB-914-000R21, SB-505-000/SB-535-000R2  
- dated 24 February 2017

## SERVICE BULLETIN

# Publication Index for ROTAX® Aircraft Engines

ATA System: 00-00-00 GENERAL NOTE

### MANDATORY

#### 1) Planning information

To obtain satisfactory results, procedures specified in this publication must be accomplished with accepted methods and prevailing legal regulations.

BRP-Rotax GmbH & Co KG. cannot accept any responsibility for the quality of work performed in accomplishing the requirements of this publication.

##### 1.1) Applicability

All engines of type:

Engine type	Serial number
912 A	(Series / Pre-series)
912 F	(Series / Pre-series)
912 S	(Series / Pre-series)
912 iSc Sport	(Series / Pre-series)
914 F	(Series / Pre-series)
505	(Series / Pre-series)
505 A	(Series / Pre-series)
535 A	(Series / Pre-series)
535 B	(Series / Pre-series)
535 C	(Series / Pre-series)

##### 1.2) Concurrent ASB/SB/SI and SL

none

##### 1.3) Reason

List of valid documentation in accordance with Part 21A.57 "Instruction for continued airworthiness".

##### 1.4) Subject

Publication Index for ROTAX® Aircraft Engines.

d06494.fm

# SERVICE BULLETIN

---

## 1.5) Compliance

### MANDATORY

For continued airworthiness keep the documentation to the latest valid revision level in accordance with the list attached and the information on the ROTAX<sup>®</sup> AIRCRAFT ENGINES homepage.



Non-compliance with these instructions could result in engine damages, personal injuries or death!

## 1.6) Approval

The technical content of this document is approved under the authority of DOA ref. EASA.21J.048.

## 2) Material Information

none

## 3) Accomplishment / Instructions

Incorporation / exchange of relevant documentation.

### 3.1) Enquiries

The following table (list of effective documentation, issue 2017.09.04, page 1-19) includes all the valid documentation for the engine types described in section 1.1).

NOTE: Because of the multitude of documentation a continual updating of the tables is not possible. This Service Bulletin, however, will be updated/revised twice a year. The current documentation (current issue) or relevant revisions (replacement pages) are available at any ROTAX<sup>®</sup> authorized distributor or their independent Service Centers in printed version or on the ROTAX<sup>®</sup> AIRCRAFT ENGINES homepage [www.FLYROTAX.com](http://www.FLYROTAX.com) (in subsection >Services >Technical Documentation) in electronic and current version.

**Symbols used** For meaning of the symbols used in this document, see chapter >Safety< in latest Operators Manual of the respective engine type.

Translation into other languages might be performed in the course of language localization but does not lie within ROTAX<sup>®</sup> scope of responsibility.

In any case the original text in English language and the metric units are authoritative.

# Publication Index for ROTAX 2-stroke aircraft engines and all versions of ROTAX aircraft engines type 912 / 912 i / 914

**ROTAX**  
AIRCRAFT ENGINES



Document Type	Engine Type	Issue	Revision	Date	Title
ASB-2ST-003,ASB-914-051UL,ASB-912-069UL	582 UL,914 UL,912 ULS,912 UL	0	1	22.07.2016	Exchange of floats on ROTAX Engine Type 912, 914 and 2-stroke (Series)
ASB-912-053	912 S,912 F,912 A	0	0	20.02.2007	Replacement of fuel pump for Rotax engine type 912 (Series) - replaced by SB-912-053, latest edition
ASB-912-053-UL	912 ULS,912 UL	0	0	20.02.2007	Replacement of fuel pump for Rotax engine type 912 (Series) - replaced by SB-912-053 UL, latest edition
ASB-912-061	912 S,912 F,912 A	0	1	31.05.2012	Replacement of the pressure side fuel hose at fuel pump part no. 893114 for ROTAX engine type 912 (Series)
ASB-912-061-UL	912 ULS,912 UL	0	1	31.05.2012	Replacement of the pressure side fuel hose at fuel pump part no. 893114 for ROTAX engine type 912 (Series)
ASB-912i-005-iS	912 iS SPORT,912 iS	0	0	29.05.2015	The use of lithium-ion batteries in combination with the ROTAX engine type 912 i Series
ASB-914-034,ASB-912-051	914 F,912 S,912 F,912 A	0	0	13.10.2006	CANCELLED - Checking of magnetic plug on Rotax engine type 912/914 (Series), replaced by SB-912-051/SB-914-034, latest edition
ASB-914-034-UL,ASB-912-051-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	13.10.2006	CANCELLED - Checking of magnetic plug on Rotax engine type 912/914 (Series), replaced by SB-912-051/SB-914-034, latest edition
ASB-914-042,ASB-912-059	914 F,912 S,912 F,912 A	0	0	01.01.2012	CANCELLED - Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series), replaced by SB-912-059/SB-914-042 latest edition
ASB-914-042-UL,ASB-912-059-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	01.01.2012	CANCELLED - Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series), replaced by SB-912-059UL/SB-914-042UL latest edition
ASB-914-043,ASB-912-060	914 F,912 S	0	0	26.01.2012	Checking of the oil pump fixing bolts for correct torque for ROTAX engine type 912 and 914 (Series)
ASB-914-043-UL,ASB-912-060-UL	914 UL,912 ULS,912 UL	0	0	26.01.2012	Checking of the oil pump fixing bolts for correct torque for ROTAX engine type 912 and 914 (Series)
ASB-914-044,ASB-912-062	914 F,912 S,912 F,912 A	0	2	29.05.2013	Checking of the cylinder head assy. 2/3 for ROTAX engine type 912 and 914 (Series)
ASB-914-044-UL,ASB-912-062-UL	914 UL,912 ULS,912 UL	0	2	29.05.2013	Checking of the cylinder head assy. 2/3 for ROTAX engine type 912 and 914 (Series)
ASB-914-051,ASB-912-069	914 F,912 S,912 F,912 A	0	1	22.07.2016	Exchange of floats on ROTAX Engine Type 912 and 914 (Series)
DIV-912 i	912 iS SPORT,912 iS,912 iSc SPORT	-	-	23.06.2016	B.U.D.S. Log Viewer (Windows) (only available for authorized distributors and overhaul facilities)
DIV-912 i	912 iS SPORT,912 iSc SPORT,912 iS	-	-	23.06.2016	B.U.D.S. Log Viewer (Linux) (only available for authorized distributors and overhaul facilities)
DIV-912 i	912 iS SPORT,912 iSc SPORT,912 iS	-	-	23.06.2016	B.U.D.S. Log Viewer (MacOs) (only available for authorized distributors and overhaul facilities)
DIV-912 i	912 iS SPORT,912 iSc SPORT,912 iS,912 iS	0	3	20.01.2014	BRP Utility and Diagnostic Software B.U.D.S. Aircraft V2.4 (Requires ROTAX USB-to-CAN activation dongle. See SI-912i-002.)

Document Type	Engine Type	Issue	Revision	Date	Title
DIV-914	914 UL,914 F	0	0	01.01.2001	Monitoring-Programm TLR 4.6a
DIV-914	914 UL,914 F	0	0	01.01.2001	Monitoring-Programm TLR 4.3a
DIV-914	914 UL,914 F	0	0	01.01.2001	Monitoring-Programm TLR 4.5a
DIV-914,DIV-912,DIV-2ST	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,642,618 UL,582 UL,535 C,535 B,535 A,532 UL,508 UL,505 A,505,503 UL,501,463,462 UL,447 UL,377 UL,277 UL,275,185	0	2	13.02.2017	Customer Service Information Report
DIV-914,DIV-912,DIV-912i,DIV-2ST	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 iSc SPORT,912 iS SPORT,912 iS,912 F,912 A,642,618 UL,582 UL,535 C,535 B,535 A,532 UL,508 UL,505 A,505,503 UL,501,463,462 UL,447 UL,377 UL,277 UL,275,185	4	0	17.02.2017	ROTAX Aircraft Engine Registration Card
HB-505	505 A	2	0	29.01.1992	Operators manual 505 A without decompressor
IM-505	505 A	1	1	01.07.1988	Installation Manual 501/505 Series (not available - use german version)
IM-535	535 C,535 B,535 A	1	1	01.12.1982	Installation Manual 535 (Series) - (not available - use german version)
IM-582,IM-503,IM-447	582 UL,503 UL,447 UL	0	0	01.05.1999	Installation Manual 447 UL SCDI-503 UL DCDI-582 UL DCDI-582 UL DCDI mod.99
IM-912	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	2	1	01.02.2015	Installation Manual ROTAX 912 Series
IM-912	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	2	1	01.02.2015	Revision Pages for Installation Manual ROTAX 912 Series, Issue 2, Revision 1
IM-912i	912 iSc SPORT,912 iS SPORT,912 iS	1	3	01.08.2015	Installation Manual ROTAX 912 i Series, Rev. 3
IM-912i	912 iSc SPORT,912 iS SPORT,912 iS	1	3	01.08.2015	Revision pages for Installation Manual ROTAX 912 i Series, Rev. 3
IM-914	914 UL,914 F	2	1	01.02.2015	Installation Manual 914 Series
IM-914	914 UL,914 F	2	1	01.02.2015	Revision Pages for Installation Manual 914 Series
IPC-277	277 UL	0	2	01.07.1993	Spare Parts List for Engine 277 UL (Nr. 491)
IPC-505	505 A	1	1	01.07.1993	Spare parts list for Engine Type 505A (Nr. 805)
IPC-505	505 A,505	0	0	01.09.1990	Spare Parts List for Engine Type 505/505A (Nr. 744)
IPC-535	535 C	0	0	01.04.1988	Illustrated Parts Catalog 535 C (Nr. 645)
IPC-535	535 B,535 A	0	0	01.07.1983	Illustrated Parts Catalog 535 A and 535 B (No. 448)
IPC-618,IPC-582,IPC-503,IPC-447	618 UL,582 UL,503 UL,447 UL	3	1	01.04.2011	Illustrated parts catalog for ROTAX 447 SCDI, 503 DCDI, 582 DCDI mod. 90, 582 DCDI mod. 99, 618 DCDI
IPC-912	912 UL	0	1	01.11.1994	Illustrated Parts Catalog 912 UL (No. 825)
IPC-912	912 A,912 UL	0	3	01.07.1992	Illustrated parts catalog 912A/912 UL (No. 825)
IPC-912i	912 iSc SPORT,912 iS SPORT,912 iS	3	1	01.03.2017	Illustrated Parts Catalog for ROTAX Engine Type 912 i Series

Document Type	Engine Type	Issue	Revision	Date	Title
IPC-914,IPC-912	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	4	1	01.03.2017	Illustrated parts catalog ROTAX 912 A/F/S/UL/ULS/ULSFR and 914 F/UL
IPC-914,IPC-912	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	4	1	01.03.2017	Exchange pages for Illustrated parts catalog ROTAX 912 A/F/S/UL/ULS/ULSFR and 914 F/UL, Edition 3, Revision 2
MM-582,MM-503,MM-447	582 UL,503 UL,447 UL	0	0	01.05.1999	Maintenance Manual 447 UL SCDI-503 UL DCDI-582 UL DCDI-582 UL DCDI mod.99
MMH-912,MMH-914	912 F,912 A,914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S	1	4	01.02.2015	Revision Pages for Maintenance Manual (Heavy) for ROTAX 912 and 914 Series, Rev. 4
MMH-912,MMH-914	912 F,912 A,914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S	1	5	15.05.2017	Maintenance Manual (Heavy) for ROTAX 912 and 914 Series
MMH-912i	912 iSc SPORT,912 iS SPORT,912 iS	1	2	01.09.2014	Revision pages for Maintenance Manual Heavy for ROTAX 912 i Series
MMH-912i	912 iSc SPORT,912 iS SPORT,912 iS	1	2	01.09.2014	Maintenance Manual (Heavy) for ROTAX 912 i Series
MML-912	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	3	2	01.02.2015	Revision Pages for Maintenance Manual 912 Series (Line Maintenance), Revision 2
MML-912	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	3	2	01.02.2015	Maintenance Manual 912 Series (Line Maintenance)
MML-912i	912 iSc SPORT,912 iS SPORT,912 iS	0	2	01.06.2014	Revision pages for Maintenance Manual (Line) for ROTAX 912 i Series, Rev. 2
MML-912i	912 iSc SPORT,912 iS SPORT,912 iS	1	2	01.06.2014	Maintenance Manual (Line) ROTAX 912 i Series
MML-914	914 UL,914 F	2	2	01.02.2015	Revision Pages for Maintenance Manual (Line) for 914 Series
MML-914	914 UL,914 F	2	2	01.02.2015	Maintenance Manual (Line) for ROTAX 914 Series
OHM-912i	912 iS SPORT,912 iSc SPORT,912 iSc,912 iS	1	0	01.04.2014	Overhaul Manual 912 i Series (only available for authorized distributors and overhaul facilities)
OHM-914,OHM-912	914 UL,914 F,912 ULS,912 UL,912 F,912 A,912 S	2	3	01.04.2015	Overhaul Manual 912 and 914 Series (only available for authorized distributors and overhaul facilities)
OHMA-912i	912 iS SPORT,912 iSc SPORT,912 iSc,912 iS	1	1	01.04.2014	Appendix to Overhaul Manual 912 i Series (only available for authorized distributors and overhaul facilities)
OHMA-914,OHMA-912	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	1	5	01.03.2016	Appendix to Overhaul Manual 912 and 914 Series (only available for authorized distributors and overhaul facilities)
OM-277	277 UL	0	4	01.03.1988	Operators manual 277 UL
OM-503,OM-447	503 UL,447 UL	19	0	01.06.1994	Operators Manual 377-447-503 UL CB
OM-505	505	2	0	30.04.1992	Operators manual 505 with decompressor
OM-505	505 A	2	0	30.04.1992	Operators manual 505 A with decompressor
OM-505	505	2	0	30.04.1992	Operators manual 505 without decompressor
OM-535	535 B,535 A	2	0	01.01.1992	Operators Manual 535 A (dual carburetor horizontal) Operators Manual 535 B (dual carburetor vertical)
OM-535	535 C	2	0	01.01.1992	Operators manual 535 C (single carburetor)
OM-582,OM-503,OM-447	582 UL,503 UL,447 UL	2	0	01.09.2010	Operators Manual for engine types 447 UL SCDI, 503 UL DCDI, 582 UL DCDI mod. 90 and 582 UL DCDI mod. 99
OM-618	618 UL	1	0	01.06.1994	Operators manual ROTAX 618 UL (preliminary)
OM-912	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	4	0	27.01.2017	Operators Manual 912 Series
OM-912i	912 iSc SPORT,912 iS SPORT,912 iS	1	3	01.08.2015	Operators Manual ROTAX 912 i Series, Rev. 2

Document Type	Engine Type	Issue	Revision	Date	Title
OM-912i	912 iSc SPORT,912 iS SPORT,912 iS	1	3	01.08.2015	Revision pages for Operators Manual ROTAX 912 i Series, Rev.3
OM-914	914 UL,914 F	2	2	01.02.2015	Revision Pages for Operators Manual 914 Series, Revision 2
OM-914	914 UL,914 F	2	2	01.02.2015	Operators Manual 914 Series
RM-277	277 UL	0	2	01.01.1993	Repair manual 277 UL
RM-503,RM-447	503 UL,447 UL	0	1	01.12.1989	Repair manual engine types 377-447-503 UL CB
RM-505	505 A,505	1	3	01.01.1993	Repair Manual 501/505 (Serie)
RM-582	582 UL	0	1	01.04.1995	Repair manual 462-532-582 UL
SB-2ST-001	582 UL	0	0	01.12.2001	Checking or replacement of tension spring on exhaust system for ROTAX engine type 582 UL
SB-2ST-002	582 UL	0	0	01.03.2002	Modified rotary valve cover for ROTAX engine type 582 UL
SB-505-001	505	0	0	26.02.1986	Studs 840 585 (M8x177) connecting cylinders to crankcase (8x)
SB-505-002	505	0	0	20.09.1988	Conversion of engine types 505 into 505 A (type certificate data sheet TW 3/78, issue no. 5
SB-505-003	505 A,505	0	0	20.09.1988	Check of ignition timing after exchange of an electronic box
SB-505-004	505 A,505	0	0	13.04.1989	Examination of the starter gear for cracks.
SB-505-005	505 A,505,501	0	0	01.08.1989	Piston pin bearing, conversion to reinforced design **(for 501 see SB-505-005)
SB-505-006	505 A,505	0	0	29.01.1992	Introduction of a new electronic box with a modified wiring on the stator plate.
SB-505-007	505 A,505,501	0	0	02.12.1997	TBO of ROTAX engine type 501, 505 and 505 A. **(for 501 see SB-505-007)
SB-505-008	505 A,505	0	0	22.01.1999	Magneto housing for ROTAX engine type 505 (series)
SB-505-009	505 A,505	0	1	01.03.2003	New charging coil assy. with support for Rotax engine type 505
SB-535-001	535 B,535 A	0	0	31.01.1984	Flywheel on drive side
SB-535-002	535 B,535 A	0	0	05.12.1985	Coil brace 866 780 connecting charging coil with lighting coil on armature plate assy.
SB-535-003	535 B,535 C,535 A	0	0	20.09.1988	Check of ignition timing after exchange of an electronic box.
SB-535-004	535 C,535 B,535 A	0	0	21.03.1989	Fixation of charging coil and lighting coil on armature plate assy.
SB-535-005	535 C,535 B,535 A	0	0	13.04.1989	Examination of the starter gear for cracks.
SB-535-006	535 C,535 B,535 A	0	0	05.06.1992	Introduction of a new electronic box with a modified wiring on the stator plate.
SB-535-007	535 B,535 A	0	1	01.02.1999	Magneto housing for ROTAX engine type 535 (Series)
SB-535-008	535 C,535 B,535 A	0	1	28.01.2005	New charging coil assy. with support for Rotax engine type 535
SB-535-009,SB-505-010,SB-501,SB-275	535 C,535 B,535 A,505 A,505,501,275	0	1	04.05.2007	New maintenance schedule, checklist and engine preservation for ROTAX engine type 275, 501, 505 and 535
SB-912-000, SB-914-000, SB-912i-000, SB-535-000,SB-505-000	535 C,535 B,535 A,505 A,505,914 F,912 S,912 F,912 A,912 iSc SPORT	0	-	04.09.2017	Publication Index for ROTAX Aircraft Engines
SB-912-000UL,SB-914-000UL,SB-912i-000iS, SB-2ST-000	912 iS,912 ULS,914 UL,447 UL,503 UL,618 UL,912 UL,912 iS SPORT,582 UL,277 UL	0	2	04.09.2017	Publication Index for ROTAX Aircraft Engines

Document Type	Engine Type	Issue	Revision	Date	Title
SB-912-001	912 A	0	0	13.08.1992	Engine type 912 A, Ignition unit with resistor spark plug
SB-912-002	912 A	0	1	29.11.1993	Ignition for ROTAX 912 A
SB-912-003	912 A	0	0	28.09.1993	CANCELLED - Operators manual for ROTAX 912 A - superseded by Operators manual 912 Series, current edition
SB-912-004	912 A	0	2	14.12.2009	Extension of time between overhauls (TBO) for ROTAX engine type 912 A (Series)
SB-912-004-UL	912 UL	0	2	14.12.2009	Extension of time between overhauls (TBO) for ROTAX engine type 912 UL (Series)
SB-912-005	912 A	0	3	14.12.2009	Special inspection to increase the TBO for ROTAX engine type 912 A (Series)
SB-912-005	912 A	0	2	29.07.1996	Special inspection to increase the TBO for engine 912 A Serie
SB-912-005-UL	912 UL	0	0	14.12.2009	Special inspection to increase the TBO for ROTAX engine type 912 UL (Series)
SB-912-006	912 A	0	0	28.11.1994	Grounding cable for electronic module of ROTAX Engine series Type 912 A
SB-912-007	912 A	0	0	01.02.1995	Ground connection for pick up wiring, ROTAX Engine Series Type 912 A
SB-912-007-UL	912 UL	0	0	20.12.2007	Ground connection for pick-up wiring for ROTAX engine type 912 (Series)
SB-912-008	912 A	0	0	24.08.1995	Electronic module with pi-filter, ROTAX Engine Series 912 A
SB-912-009	912 A	0	0	12.09.1995	Contamination of carburetors, ROTAX 912 A (series)
SB-912-010	912 F,912 A	0	0	08.02.1996	Fitting of a carburetor support, ROTAX 912 A/F (series)
SB-912-010-UL	912 UL	0	0	20.12.2007	Fitting of a carburetor support for ROTAX engine type 912 (Series)
SB-912-011	912 F,912 A	0	1	01.11.1999	CANCELLED - Use of an adapted propeller governor on Rotax engine type 912 A3 and 912 F3, superseded by SB-912-052/SB-914-035, latest edition
SB-912-012	912 A	0	0	13.08.1996	Modification on ROTAX 912 A4
SB-912-013	912 ULS,912 UL,912 S,912 F,912 A	0	0	29.07.1996	CANCELLED - Motor oil for ROTAX 912 Series - superseded by SI-18-1997 latest edition
SB-912-014	912 F,912 A	0	2	14.12.2009	Extension of time between overhauls (TBO) for ROTAX engine type 912 A and 912 F (Series)
SB-912-015	912 F,912 A	0	0	29.07.1996	Replacement of rocker arms on ROTAX 912 A/F (series)
SB-912-015-UL	912 UL	0	0	20.12.2007	Replacement of rocker arms for ROTAX engine type 912 (Series)
SB-912-016	912 A	0	0	13.08.1996	External alternator for engine type 912, model A2, A3 and A4
SB-912-017,SB-914-037	912 F,912 A,914 F	0	-	20.12.2007	Checking or replacement of oil filter for ROTAX engine type 912 and 914 (Series)
SB-912-017-UL,SB-914-037-UL	912 UL,914 UL	0	-	20.12.2007	Checking or replacement of oil filter for ROTAX engine type 912 and 914 (Series)
SB-912-018	912 A	0	1	18.03.1997	Cam shaft check engine type ROTAX 912 A (series)
SB-912-019	912 A	0	0	09.07.1997	Propeller gear box for ROTAX 912 A3
SB-912-020	912 F,912 A	0	1	10.02.1998	Fuel pump for Engine type ROTAX 912 F and 912 A (series)
SB-912-020-UL	912 UL	0	0	20.12.2007	Replacement of the fuel pump part no. 996592 for ROTAX engine type 912 (Series)
SB-912-021	912 F	0	0	17.12.1997	CANCELLED - Operator's manual for ROTAX 912 F - superseded by Operator's manual 912 Series, latest edition
SB-912-022,SB-914-011	912 S,912 F,912 A,914 F	0	0	01.03.2001	Replacement of valve spring retainer on single valve spring configuration of ROTAX engine type 912 und 914 (series)

Document Type	Engine Type	Issue	Revision	Date	Title
SB-912-022-UL,SB-914-011-UL	912 ULSFR,912 ULS,912 UL,914 UL	0	1	13.03.2001	Replacement of valve spring retainer on single valve spring configuration of ROTAX engine type 912 und 914 (Series)
SB-912-023	912 F,912 A	0	0	25.05.1998	Inspection of the fuel pump kit, part no. 996.594
SB-912-024	912 F,912 A	0	0	22.10.1998	CANCELLED - Installation of propeller governor McCauley DCFU290D17B/T1, superseded by SB-912-052/SB-914-035, latest edition
SB-912-025	912 F,912 A	0	0	22.10.1998	CANCELLED - Installation of propeller governor McCauley DCFU290D17B/T2, superseded by SB-912-052/SB-914-035, latest edition
SB-912-026,SB-914-014	912 F,912 A,914 F	0	3	01.12.1999	Checking and replacement of stator assy.
SB-912-026-UL,SB-914-014-UL	912 ULS,912 UL,914 UL	0	3	01.12.1999	Checking and replacement of stator assy.
SB-912-027,SB-914-010	912 F,912 A,914 F	0	1	01.02.2000	Checking or replacement of the propeller gearbox for all versions of the Rotax engine type 912 and 914
SB-912-027-UL,SB-914-010-UL	912 UL,914 UL	0	1	01.02.2000	Checking or replacement of the propeller gearbox for all versions of the Rotax engine type 912 and 914
SB-912-028,SB-914-016	912 S,912 F,912 A,914 F	0	1	01.11.2002	Checking or replacement of engine suspension frame part no. 886 567 on ROTAX engine type 912 and 914 (Series)
SB-912-028-UL,SB-914-016-UL	912 ULSFR,912 ULS,912 UL,914 UL	0	1	01.11.2002	Checking or replacement of engine suspension frame part no. 886 567 on ROTAX engine type 912 and 914 (series)
SB-912-029,SB-914-018	912 S,912 F,912 A,914 F	0	3	11.07.2006	Checking of crankcase on ROTAX engine type 912 and 914 (Series)
SB-912-029-UL,SB-914-018-UL	912 ULS,912 ULSFR,912 UL,914 UL	0	3	11.07.2006	Checking of the crankcase on ROTAX engine type 912 and 914 (Series)
SB-912-030,SB-914-019	912 S,912 F,912 A,914 F	0	1	01.02.2004	Cracks, wear and distortion on the carburetor flange on Rotax engine type 912 and 914 (series)
SB-912-030-UL,SB-914-019-UL	912 ULS,912 ULSFR,912 UL,914 UL	0	1	01.02.2004	Cracks, wear and distortion on the carburetor flange on Rotax engine type 912 and 914 (series)
SB-912-031	912 S,912 F,912 A	0	0	01.10.2001	Checking or replacement of the fuel pump assembly part no. 996 596 on ROTAX engine tpye 912 (series)
SB-912-031-UL	912 ULSFR,912 ULS,912 UL	0	0	01.10.2001	Checking or replacement of the fuel pump assembly part no. 996 596 on ROTAX engine tpye 912 (series)
SB-912-032	912 A	0	0	01.10.2001	Replacement of oil pump assy. or oil pump shaft assy. on ROTAX engine type 912 A (series)
SB-912-032-UL	912 UL	0	0	01.10.2001	Replacement of oil pump assy. or oil pump shaft assy. on ROTAX engine type 912 UL
SB-912-033,SB-914-020	912 S,912 F,912 A,914 F	0	0	01.08.2002	Inspection of the propeller gearbox when using leaded fuel for ROTAX engine 912/914
SB-912-033-UL,SB-914-020-UL	912 ULSFR,912 ULS,912 UL,914 UL	0	0	01.08.2002	Inspection of the propeller gearbox when using leaded fuel for ROTAX engine 912/914
SB-912-034	912 A	0	0	01.03.2002	Checking of oil pump attachment screw for ROTAX engine type 912 A (Series)
SB-912-034-UL	912 UL	0	0	01.03.2002	Checking of oil pump attachment screw for ROTAX engine type 912 UL (Series)



Document Type	Engine Type	Issue	Revision	Date	Title
SB-912-035,SB-914-021	912 S,912 F,912 A,914 F	0	1	01.09.2002	Inspection or replacement of the rocker arms and valve push-rods for Rotax engine type 912 and 914 (Series)
SB-912-035-UL,SB-914-021-UL	912 ULSFR,912 ULS,912 UL,914 UL	0	1	01.09.2002	Inspection or replacement of the rocker arms and valve push-rods for Rotax engine type 912 and 914 (Series)
SB-912-036,SB-914-022	912 S,912 F,912 A,914 F	0	1	23.01.2007	CANCELLED - Inspection for correct venting of the oil system for Rotax engine type 912 and 914 (Series), superseded by SB-912-040/SB-914-026, latest edition
SB-912-036-UL,SB-914-022-UL	912 ULSFR,912 ULS,912 UL,914 UL	0	1	23.01.2007	CANCELLED - Inspection for correct venting of the oil system for Rotax engine type 912 and 914 (Series), superseded by SB-912-040UL/SB-914-026UL, latest edition
SB-912-037,SB-914-023	912 S,912 F,912 A,914 F	0	1	01.10.2003	Installation of an electric starter with enhanced power for Rotax Motor Type 912 und 914 (Serie)
SB-912-037-UL,SB-914-023-UL	912 ULS,912 UL,912 ULSFR,914 UL	0	0	01.10.2002	Installation of an electric starter with enhanced power for Rotax Motor Type 912 und 914 (Serie)
SB-912-038,SB-914-024	912 S,912 F,912 A,914 F	0	0	01.11.2002	CANCELLED - Revision of Operators Manual for ROTAX engine type 912 and 914 (Series)
SB-912-042	912 S	0	1	01.04.2004	Checking of the engine in case of excessive propeller backlash for Rotax engine type 912 S
SB-912-042-UL	912 ULSFR,912 ULS	0	1	01.04.2004	Checking of the engine in case of excessive propeller backlash for Rotax engine type 912 S
SB-912-044	912 F,912 A	0	1	28.05.2010	Use of the Rotax supplied airbox for all Rotax engine types 912 A/F (Series)
SB-912-044-UL	912 UL	0	1	28.05.2010	Use of the Rotax supplied airbox for all Rotax engine types 912 UL (Series)
SB-912-049	912 S,912 F,912 A	0	0	24.05.2006	Checking eccenters and fuel pump plungers for Rotax engine type 912 (series)
SB-912-049-UL	912 ULS,912 ULSFR,912 UL	0	0	24.05.2006	Checking eccenters and fuel pump plungers for Rotax engine type 912 (series)
SB-912-050	912 S,912 F,912 A	0	0	24.05.2006	CANCELLED - Checking or replacement of fuel pump part no. 892230/892235 on Rotax engine type 912 (series), superseded by ASB-912-053 latest edition
SB-912-050-UL	912 ULS,912 ULSFR,912 UL	0	0	24.05.2006	CANCELLED - Checking or replacement of fuel pump part no. 892230/892235 on Rotax engine type 912 (series), superseded by ASB-912-053 latest edition
SB-912-053	912 S,912 F,912 A	0	0	13.04.2007	Replacement of fuel pump for Rotax engine type 912 (Series)
SB-912-053-UL	912 ULSFR,912 ULS,912 UL	0	0	13.04.2007	Replacement of fuel pump for Rotax engine type 912 (Series)
SB-912-054	912 S,912 F,912 A	0	0	29.05.2007	Checking or replacement of flexible fuel line for Rotax engine type 912 (Series)
SB-912-054-UL	912 ULSFR,912 ULS,912 UL	0	0	29.05.2007	Checking or replacement of flexible fuel line for Rotax engine type 912 (Series)
SB-912-057	912 S,912 F,912 A	0	1	24.05.2016	Extension of Time Between Overhauls (TBO) for ROTAX Engine Type 912 (Series)
SB-912-057-UL	912 ULSFR,912 ULS,912 UL	0	0	14.12.2009	Extension of time between overhauls (TBO) for ROTAX engine type 912 (Series)
SB-912-063	912 S,912 F,912 A	0	1	24.06.2013	Replacement of Fuel Pumps for Rotax Engine Type 912 (Series)
SB-912-063-UL	912 ULS,912 UL,912 ULSFR	0	2	21.08.2013	Replacement of Fuel Pumps for Rotax Engine Type 912 (Series)
SB-912-064,SB-914-045	912 S,912 F,912 A,914 F	0	1	11.11.2013	Periodic checking of the crankshaft journal (power take off side) for ROTAX Engine Type 912 and 914 (Series)

Document Type	Engine Type	Issue	Revision	Date	Title
SB-912-064-UL,SB-914-045-UL	912 ULS,912 ULSFR,912 UL,914 UL	0	1	11.11.2013	Periodic checking of the crankshaft journal (power take off side) for ROTAX Engine Type 912 and 914 (Serie)
SB-912-065 UL,SB-914-046 UL	912 UL,914 UL,912 ULS	0	3	26.03.2015	Periodic inspection of the float buoyancy for ROTAX Engine Type 912 and 914 (Series)
SB-912-065,SB-914-046	912 S,912 F,912 A,914 F	0	3	26.03.2015	Periodic inspection of the float buoyancy for ROTAX Engine Type 912 and 914 (Series)
SB-912-066,SB-914-047	912 S,912 F,912 A,914 F	0	1	23.04.2015	Change of Measurement Method from Cylinder Head Temperature to Coolant Temperature for ROTAX® Engine Type 912 and 914 (Series)
SB-912-066-UL,SB-914-047-UL	912 ULSFR,912 ULS,912 UL,914 UL	0	1	23.04.2015	Change of Measurement Method from Cylinder Head Temperature to Coolant Temperature for ROTAX® Engine Type 912 and 914 (Series)
SB-912-067,SB-914-048	912 S,912 F,912 A,914 F	0	1	26.03.2015	Exchange of floats on ROTAX Engine Type 912 and 914 (Series)
SB-912-067-UL,SB-914-048-UL	912 ULSFR,912 ULS,912 UL,914 UL	0	1	26.03.2015	Exchange of floats on ROTAX Engine Type 912 and 914 (Series)
SB-912-068,SB-914-049	912 S,912 F,912 A,914 F	0	1	09.09.2015	Specification/Change of Engine Configuration and/or Type Plate for ROTAX Engine Type 912 and 914 (Series)
SB-912-068-UL,SB-914-049-UL	912 ULSFR,912 ULS,912 UL,914 UL	0	2	09.09.2015	Specification/Change of Engine Configuration and/or Type Plate for ROTAX Engine Type 912 and 914 (Series)
SB-912i-001,SB-914-035,SB-912-052	912 iSc SPORT,914 F,912 S,912 F,912 A	0	-	13.06.2014	Installation / Use of governors for Rotax engine type 912i, 912 and 914
SB-912i-001iS,SB-914-035-UL,SB-912-052-UL	912 iS,914 UL,912 ULSFR,912 ULS,912 UL,912 iS SPORT	0	-	13.06.2014	Installation / Use of governors for Rotax engine type 912i, 912 and 914 (Series)
SB-912i-002iS	912 iS	0	0	18.12.2013	Flashing of a new Software on the Engine Control Unit 912 iS (ECU) for ROTAX Engine Type 912 i (Series)
SB-912i-003iS	912 iS	0	1	03.06.2014	Installation instructions for upgrade kit 912 iS Sport for ROTAX engine type 912 i (Series)
SB-912i-004iS	912 iS	0	0	03.09.2014	Replacement of Regulator A and Regulator B for ROTAX Engine Type 912 i (Series)
SB-912i-006	912 iSc SPORT	0	0	26.05.2016	Exchange of stator assy. of ROTAX Engine Type 912 i (Series)
SB-912i-006iS	912 iS SPORT,912 iS	0	0	26.05.2016	Exchange of stator assy. of ROTAX Engine Type 912 i (Series)
SB-914-001	914 F	0	0	06.02.1997	CANCELLED - Use of an adapted propeller governor on engine type ROTAX 914 F3, superseded by SB-912-052/SB-914-035, latest edition
SB-914-002	914 F	0	0	24.02.1997	Modification of engine type ROTAX 914 F3
SB-914-003	914 F	0	0	09.07.1997	Calibration of the mixture enrichment jet of engine type ROTAX 914 F (series)
SB-914-003-UL	914 UL	0	0	20.12.2007	Calibration of the mixture enrichment jet for ROTAX engine type 914 (Series)
SB-914-004	914 F	0	0	27.08.1997	Checking of the banjo bolt in the pressure oil line of turbo charger for ROTAX 914 (series)
SB-914-004-UL	914 UL	0	0	20.12.2007	Checking of the banjo bolt in the pressure oil line of turbocharger for ROTAX engine type 914 (Series)
SB-914-005	914 F	0	0	29.07.1998	Introduction of a turbo charger with a modified wastegate on Rotax 914

Document Type	Engine Type	Issue	Revision	Date	Title
SB-914-005-UL	914 UL	0	0	20.12.2007	Introduction of a turbocharger with modified waste-gate for ROTAX engine type 914 (Series)
SB-914-006	914 F	0	1	01.10.2002	Employment of a muffler of reduced noise emission on ROTAX engine Type 914 F (series).
SB-914-006-UL	914 UL	0	0	01.10.2002	Employment of a muffler of reduced noise emission on ROTAX engine Type 914 F (series).
SB-914-007	914 F	0	0	05.06.1998	ROTAX engine type 914 F (series), check / replacement of the turbo oil pressure line and pipe clamps
SB-914-007-UL	914 UL	0	0	20.12.2007	Check/replacement of the turbo oil pressure line and pipe clamps for ROTAX engine type 914 (Series)
SB-914-008	914 F	0	0	05.06.1998	ROTAX engine type 914 F (series) check / replacement of the wastegate servo cable
SB-914-008-UL	914 UL	0	0	20.12.2007	Check/replacement of the waste-gate servo cable for ROTAX engine type 914 (Series)
SB-914-009	914 F	0	0	22.10.1998	CANCELLED - Installation of propeller governor McCauley DCFU290D17B/T2, superseded by SB-912-052/SB-914-035, latest edition
SB-914-012	914 F	0	0	29.09.1998	ROTAX engine series type 914 F, verification of the wiring harness
SB-914-012-UL	914 UL	0	0	20.12.2007	Verification of the wiring harness for ROTAX engine type 914 (Series)
SB-914-013	914 F	0	0	31.03.1999	Turbocharge control unit (TCU) with software level according to RTCA DO 178 B, for engine Type 914 F (series)
SB-914-013-UL	914 UL	0	0	20.12.2007	Turbocharge control unit (TCU) with software level D according to RTCA DO 178 B for ROTAX engine type 914 (Series)
SB-914-015	914 F	0	0	01.01.2001	Checking or replacement of the exhaust muffler of reduced noise emission part no. 979405 for ROTAX engine type 914 F
SB-914-017	914 F	0	1	01.07.2002	Checking or replacement of exhaust bend on ROTAX engine type 914 (Series)
SB-914-017-UL	914 UL	0	1	01.07.2002	Checking or replacement of the exhaust bend on ROTAX engine type 914 (series)
SB-914-024-UL, SB-912-038-UL	914 UL, 912 ULSFR, 912 ULS, 912 UL	0	0	01.11.2002	CANCELLED - Revision of Operators Manual for ROTAX engine type 912 and 914 (Series)
SB-914-025, SB-912-039	914 F, 912 S, 912 F, 912 A	0	0	01.12.2002	Modifications of the overflow bottle for ROTAX engine type 912 and 914 (Series)
SB-914-025-UL, SB-912-039-UL	914 UL, 912 ULSFR, 912 ULS, 912 UL	0	0	01.12.2002	Modifications of the overflow bottle for ROTAX engine type 912 and 914 (Series)
SB-914-026, SB-912-040	914 F, 912 S, 912 F, 912 A	0	1	01.08.2003	Introduction of a new oil dipstick for ROTAX engine type 912 and 914 (Series)
SB-914-026-UL, SB-912-040-UL	914 UL, 912 ULSFR, 912 ULS, 912 UL	0	0	01.04.2003	Introduction of a new oil dipstick for ROTAX engine type 912 and 914 (Series)
SB-914-027, SB-912-041	914 F, 912 S, 912 F, 912 A	0	2	25.03.2010	Extension of Time Between Overhaul (TBO) for ROTAX engine type 912 and 914 (Series)
SB-914-027-UL, SB-912-041-UL	914 UL, 912 ULSFR, 912 ULS, 912 UL	0	2	25.03.2010	Extension of Time Between Overhaul (TBO) for ROTAX engine type 912 and 914 (Series)
SB-914-028	914 F	0	1	08.11.2004	Inspection of exhaust muffler part no. 979402 / 979404 for Rotax engine type 914 (Series)
SB-914-028-UL	914 UL	0	1	08.11.2004	Inspection of exhaust muffler part no. 979402 / 979404 for Rotax engine type 914 (Series)

Document Type	Engine Type	Issue	Revision	Date	Title
SB-914-029,SB-912-043	914 F,912 S,912 F,912 A	0	2	10.11.2006	Change of coolant specification on ROTAX engine type 912 and 914 (Series)
SB-914-029-UL,SB-912-043-UL	914 UL,912 ULSFR,912 ULS,912 UL	0	1	28.08.2006	Change of coolant specification on ROTAX engine type 912 and 914 (Series)
SB-914-030,SB-912-045	914 F,912 S,912 F,912 A	0	0	19.11.2004	Inspection of the oil filter part no. 825701 for Rotax engine type 912 and 914 (Series)
SB-914-030-UL,SB-912-045-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	19.11.2004	Inspection of the oil filter part no. 825701 for Rotax engine type 912 and 914 (Series)
SB-914-031,SB-912-046	914 F,912 S	0	0	26.07.2005	Check of the support bearing on the crankshaft and of the bearing bushing in the propeller gearbox on Rotax engine type 912/914 (Series)
SB-914-031-UL,SB-912-046-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	26.07.2005	Check of support bearing on the crankshaft and of the bearing bushing in the propeller gearbox on Rotax engine type 912/914 (Series)
SB-914-032,SB-912-047	914 F,912 S	0	0	29.07.2005	Check of Allen screw M8x100 in the crankcase on Rotax engine type 912/914 (Series)
SB-914-032-UL,SB-912-047-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	29.07.2005	Check of Allen screw M8x100 in the crankcase on Rotax engine type 912/914 (Series)
SB-914-033,SB-912-048	914 F,912 S,912 F,912 A	0	0	23.09.2005	Replacement of pin part no. 929700 in carburetor for Rotax engine type 912 and 914 (series)
SB-914-033-UL,SB-912-048-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	23.09.2005	Replacement of pin part no. 929700 in carburetor for Rotax engine type 912 and 914 (series)
SB-914-034,SB-912-051	914 F,912 S,912 F,912 A	0	0	30.01.2008	Checking of magnetic plug on Rotax engine type 912/914 (Series)
SB-914-034-UL,SB-912-051-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	30.01.2008	Checking of magnetic plug on Rotax engine type 912/914 (Series)
SB-914-036,SB-912-055	914 F,912 S,912 F,912 A	0	0	31.08.2007	Inspect for tight fit of oil filter for Rotax engine type 912 and 914 (Series)
SB-914-036-UL,SB-912-055-UL	914 UL,912 ULSFR,912 ULS,912 UL	0	0	31.08.2007	Inspect for tight fit of oil filter for Rotax engine type 912 and 914 (Series)
SB-914-038,SB-912-056	914 F,912 S	0	1	05.08.2008	Replacement of the propeller gearbox for some Rotax engines type 912/914 (Series)
SB-914-038-UL,SB-912-056-UL	914 UL,912 ULSFR,912 ULS	0	1	05.08.2008	Replacement of the propeller gearbox for some ROTAX engines type 912/914 (Series)
SB-914-039	914 F	0	0	25.03.2010	Extension of time between overhauls (TBO) for ROTAX engine type 914 (Series)
SB-914-039-UL	914 UL	0	0	25.03.2010	Extension of time between overhauls (TBO) for ROTAX engine type 914 (Series)
SB-914-040	914 F	0	0	10.03.2011	Replacement of fuel pressure regulator part no. 887130 for ROTAX engine type 914 (Series)
SB-914-040-UL	914 UL	0	0	10.03.2011	Replacement of fuel pressure regulator assy. part no. 887130 for ROTAX engine type 914 (Series)
SB-914-041,SB-912-058	914 F,912 S,912 F,912 A	0	0	15.04.2011	Replacement of washer part no. 944072 (flywheel hub) for ROTAX engine type 912 and 914 (Series)

Document Type	Engine Type	Issue	Revision	Date	Title
SB-914-041-UL,SB-912-058-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	15.04.2011	Replacement of washer part no. 944072 (flywheel hub) for ROTAX engine type 912 and 914 (Series)
SB-914-042,SB-912-059	914 F,912 S,912 F,912 A	0	0	01.01.2012	Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series)
SB-914-042-UL,SB-912-059-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	01.01.2012	Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series)
SB-914-050	914 F	0	0	13.05.2015	Replacement of the overload clutch of ROTAX® Engine Type 914 (Series)
SB-914-050-UL	914 UL	0	0	13.05.2015	Replacement of the overload clutch of ROTAX® Engine Type 914 (Series)
SI-01-1985	532 UL,503 UL,462 UL,447 UL,377 UL	0	0	01.04.1985	UL-Propeller-Gear
SI-01-1988	532 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.01.1988	Function test of rectifier regulator
SI-01-1989	503 UL	0	0	01.03.1989	Fan drive of engine Type 503
SI-01-1991	582 UL,532 UL	0	0	01.02.1991	Rotary valve shaft sealing for ROTAX 532 UL and 582 UL
SI-01-1992	912 UL	0	0	01.07.1992	Engine type 912 UL, ignition unit with resistor spark plug
SI-01-1993	582 UL	0	0	01.01.1993	ROTAX 582 UL DCDI - making of pick-up
SI-01-1994	912 A,912 UL	0	0	01.01.1994	Electronic-box for ROTAX 912 A + UL
SI-01-1995	912 UL	0	1	01.04.1995	CANCELLED - Ground connection for pick-up wiring, ROTAX engine Series Type 912 UL, superseded by SB-912-007 UL, latest edition
SI-01-1998	912 UL	0	1	01.02.1998	CANCELLED - Fuel pump 996592 (pump with screw fittings) 912 (series), superseded by SB-912-020 UL, latest edition
SI-02-1984	277 UL	0	0	25.01.1984	UL-Propeller-Gear 277
SI-02-1985	532 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.05.1985	Increase of ignition voltage on BOSCH contact ignition
SI-02-1991	618 UL,582 UL,503 UL	0	0	01.02.1991	Tightening torque increase on 'C' gearboxes for UL-engines.
SI-02-1992	912 A,912 UL	0	0	01.12.1992	Coolant expansion tank ROTAX 912
SI-02-1995	912 A,912 ULSFR,912 ULS,912 UL,912 S,912 F	2	0	01.08.1995	Contamination of carburetors, ROTAX-series 912
SI-02-1996	912 UL,912 A	0	0	01.02.1996	Rectifier regulator, Rotax Series 912
SI-02-1997	912 UL	0	0	01.02.1997	Camshaft check on ROTAX engine Type 912 UL (series)
SI-02-1998	914 F,914 UL	0	0	01.06.1998	CANCELLED - ROTAX engine type 914, check / replacement of the turbo oil pressure line and pipe clamps, superseded by SB-914-007 UL, latest edition
SI-03-1985	277 UL	0	0	01.09.1985	UL-Propeller-Gear 277
SI-03-1985	277 UL	0	0	01.09.1985	UL-Propeller Gear 277
SI-03-1989	532 UL,503 UL,447 UL,377 UL	0	0	01.06.1989	Matching a propeller to ROTAX UL-Engines.
SI-03-1991	618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.04.1991	Daily and Pre-Flight-Check - Maintenance plan for all ROTAX engines
SI-03-1993	912 UL	0	0	01.02.1993	Ignition unit of ROTAX 912 UL
SI-03-1994	912 UL,912 A	0	0	01.12.1994	Sensor and gauge for oil pressure indication-ROTAX 912
SI-03-1996	618 UL,582 UL,532 UL,462 UL	0	1	01.09.1999	Rotary valve shaft seal leakage at Rotax engine type 462 UL / 532 UL / 582 UL and 618 UL

Document Type	Engine Type	Issue	Revision	Date	Title
SI-03-1997	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	1	01.01.1999	CANCELLED - Coolant (antifreeze) mixtures for ROTAX engine type 912/914 (Series) - superseded by relevant Operators Manual, latest edition
SI-03-1998	914 UL,914 F,912 UL,912 S,912 F,912 A	0	1	01.02.2004	Engine start at low temperatures at Rotax engine type 912 and 914 (Series)
SI-03-1999	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	0	01.02.1999	Standardization of the crankcase for ROTAX engines 912 and 914
SI-04-1986	532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.09.1986	Possible causes for piston seizures or holes in pistons
SI-04-1987	582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	1	0	01.05.1990	Ultralight engines-unexpected engine stops
SI-04-1989	582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.01.1989	Use of tool for cageless piston pin needle bearing
SI-04-1990	582 UL	0	0	01.09.1990	Starter gear - electric starter, magneto side, on engine 582 UL
SI-04-1993	582 UL	0	0	01.09.1993	Crankcase modifications - ROTAX 582 DCDI
SI-04-1994	532 UL,914 UL,912 UL,618 UL,582 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.02.1994	Carburetor icing on UL-engines
SI-04-1995	912 F,912 A,912 UL	0	0	01.05.1995	Floats with a new shape, engine Series Type 912
SI-04-1997	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	3	23.01.2007	CANCELLED - Venting of lubrication system for Rotax engine type 912 and 914 (Series), superseded by SI-912-018/SI-914-020, latest edition
SI-04-1998	914 F,914 UL	0	1	01.06.1998	CANCELLED - ROTAX engine type 914 F (series) Replacement of the waste gate servo cable, superseded by SB-914-008 UL, latest edition
SI-05-1988	447 UL,532 UL,503 UL,462 UL,377 UL	0	0	01.04.1990	Gearbox fixation on UL-engines type 377 to 532 UL
SI-05-1990	582 UL,503 UL	0	1	01.12.1990	Disturbance of tachometer 966 072 for 503 UL C.D.I. and 582 UL with DUCATI ignition unit
SI-05-1991	618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.12.1991	Piston for ROTAX UL engines (2-stroke)
SI-05-1994	912 UL,912 A	0	0	01.03.1994	Banjo Bolt ROTAX 912
SI-05-1995	912 UL	0	2	01.07.1996	External alternator for engine series type 912 UL, Mod. 94
SI-05-1996	503 UL,447 UL	0	0	01.03.1997	Cracks in the carburetor socket, ROTAX 447 and 503 UL
SI-05-1997	914 UL,914 F,912 UL,912 F,912 A	0	1	01.04.1997	Exhaust flange of ROTAX engines 912/914 (series)
SI-05-1998	914 UL,914 F	0	0	01.06.1998	Acceptable cracks in the turbine housing of the turbo charger for engine 914
SI-05-1999	914 UL	0	0	01.10.1999	CANCELLED - Turbocharge control unit (TCU) with software level according to RTCA DO 178 B, for ROTAX engine Type 914 F (series), superseded by SB-914-013 UL, latest edition
SI-06-1986	377 UL,277 UL,532 UL,508 UL,503 UL,462 UL,447 UL	0	0	01.12.1986	UL-Reduction gear box
SI-06-1987	582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.07.1987	Engine-Instruments
SI-06-1993	582 UL	0	0	01.09.1993	ROTAX 582 UL carb adapter

Document Type	Engine Type	Issue	Revision	Date	Title
SI-06-1994	618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.07.1994	Incorrect Model fuel pumps without bleed hole, ROTAX 2-cycle engines
SI-06-1995	912 UL	0	2	01.07.1996	External alternator for engine series type 912 UL, Mod. 89 and 91
SI-06-1996	618 UL,582 UL,503 UL	0	0	01.03.1997	Modifications on reduction gearbox 'C' and 'E'
SI-06-1997	914 UL,914 F,912 UL,912 F,912 A	0	1	18.02.2005	Friction torque check of propeller gear with overload clutch on Rotax engine type 912 and 914 (Series)
SI-06-1998	618 UL,582 UL,532 UL,503 UL,447 UL	0	1	01.07.2001	Amendment on reduction gearbox type 'C' and type 'E' for 2-stroke UL aircraft engines
SI-06-1999	912 ULS,912 S	0	0	01.01.1998	ROTAX engine Type 912 ULS/S, Oil consumption
SI-07-1987	582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	1	0	01.04.1990	Fuel consumption, 2-stroke UL-Engine
SI-07-1991	508 UL,447 UL	0	0	01.05.1991	Wiring diagr. for 447 UL SCDI and 508 UL SCDI in conj. with electr. tachometer
SI-07-1993	447 UL	0	0	01.09.1993	Revolution counter for ROTAX 447 SCDI
SI-07-1994	582 UL	0	0	01.07.1994	ROTAX 582 UL crankshaft
SI-07-1995	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A,618 UL,582 UL,532 UL,503 UL,447 UL,377 UL,277 UL	0	1	01.02.1999	New airfilter with securing tab
SI-07-1996	912 UL	0	0	01.09.1996	CANCELLED - Replacement of rocker arms on ROTAX 912 UL (series), superseded by SB-912-015 UL, latest edition
SI-07-1997	914 UL	0	0	01.07.1997	CANCELLED - Calibration of the mixture enrichment jet of ROTAX 914 UL (series), superseded by SB-914-003 UL, latest edition
SI-07-1998	503 UL	0	0	12.10.1998	'B' type gearbox installation, ROTAX 503 UL DCDI (all versions)
SI-08-1987	582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.06.1990	Influence of ambient air temperature and barometric pressure on engine performance and carb calibration
SI-08-1991	618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.06.1991	Safety-check of the BING-carburetors used in all ROTAX UL-engines
SI-08-1993	912 UL,912 A	0	0	01.10.1993	CANCELLED - General overhaul of ROTAX 912 A/UL, superseded by SB for TBO Extension, latest edition
SI-08-1994	582 UL	0	0	01.05.1994	Attaching of water pump housing on ROTAX 582 UL
SI-08-1995	912 UL	0	1	01.12.1995	CANCELLED - Fitting of a carburetor support, Rotax Series 912, superseded by SB-912-010 UL, latest edition
SI-08-1996	618 UL	0	0	01.03.1997	Installation of oversize pistons, ROTAX 618 UL
SI-08-1998	914 UL	0	1	01.02.1999	CANCELLED - ROTAX engine series type 914 UL, verification of the wiring harness, superseded by SB-914-012 UL, latest edition
SI-08-1999	582 UL,503 UL,447 UL	0	0	01.02.1999	CANCELLED - Documentations for 447 - 503 - 582 - 582 Mod. 99, superseded by SL-2ST-002, latest edition
SI-09-1991	618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.11.1991	Installation Instructions for ROTAX UL-engines
SI-09-1993	618 UL	0	0	01.11.1993	Assembly instructions for ROTAX 618 water pump cover
SI-09-1994	618 UL,582 UL,532 UL,503 UL	0	2	01.01.2004	Installation Instruction of UL reduction gearbox type 'C' and 'CL'

Document Type	Engine Type	Issue	Revision	Date	Title
SI-09-1996	914 UL	0	0	01.03.1998	ROTAX 914 UL exchange of the oilpump housing
SI-09-1997	503 UL	0	0	01.07.1997	Exchange of piston pins, ROTAX 503 UL
SI-10-1987	503 UL	0	0	01.11.1987	503 UL- FREE AIR Version
SI-10-1991	912 A,912 UL	0	0	01.09.1991	Water distributor for ROTAX 912 A and 912 UL
SI-10-1994	618 UL,582 UL,532 UL,503 UL	0	2	01.01.2004	Installation Instruction of UL reduction gearbox type 'E' and 'EL'
SI-10-1996	618 UL,582 UL,532 UL,503 UL,447 UL,377 UL,277 UL	0	0	01.05.1997	Piston pin circlip installation (2-stroke UL-engines)
SI-10-1999	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	0	01.03.1999	Illustrated Parts Catalog (IPC) for ROTAX engines 912 / 914 (series)
SI-11-1987	532 UL,503 UL,447 UL,377 UL	0	0	01.11.1987	Exhaust systems for 377/447/462/503/532
SI-11-1991	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.12.1992	Propeller mass moment of inertia
SI-11-1994	503 UL	1	0	01.06.1994	Subsequent install. or retrofit of an oil-Pump for separate oil Lubrication
SI-11-1996	618 UL,582 UL,532 UL,503 UL,447 UL,377 UL,277 UL	0	0	01.01.1998	Engine preservation for 2-stroke- UL- engines
SI-11-1997	914 UL,914 F	0	0	01.12.1997	Adjustment or verification of the wastegate position on ROTAX 914
SI-12-1991	508 UL	0	0	01.12.1992	508 UL-Valve Cover Attachment
SI-12-1994	462 UL,447 UL,377 UL,277 UL,582 UL,532 UL,508 UL,503 UL	0	2	01.01.2004	Installation Instruction of UL reduction gearbox Type 'B'
SI-12-1996	914 F,914 UL,912 F,912 A,912 UL	0	0	01.12.1996	CANCELLED - Oil filter ROTAX 912 / 914 engine, superseded by SB-912-017/SB-914-037 UL, latest edition
SI-12-1997	914 F,914 UL	0	0	01.07.1997	CANCELLED - Checking of the banjo bolt in the pressure oil line of turbo charger for ROTAX engine Type 914 (series), superseded by SB-914-004 UL, latest edition
SI-13-1994	618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.07.1994	Using auto fuel in ROTAX two cycle aircraft engine
SI-13-1996	914 UL,914 F,912 UL,912 F,912 A	0	2	23.06.2009	Installation instructions of rev-counter part no. 966403 and 966408 for Rotax engine type 912 and 914 (Series)
SI-13-1997	914 F,914 UL	0	0	01.12.1997	CANCELLED - Introduction of a turbo charger with a modified wastegate on Rotax 914, superseded by SB-914-005 UL, latest edition
SI-14-1994	618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.07.1994	ROTAX two-cycle aircraft engines crankshaft failures, piston seizures
SI-14-1997	912 UL,914 F,914 UL,912 F,912 A	0	1	01.03.1998	Introduction of the single valve spring arrangement on Rotax engine type 912 and 914 (series)
SI-15-1994	618 UL,582 UL,532 UL,508 UL,503 UL,447 UL	0	0	01.11.1995	Rev. counter for DUCATI ignition unit



Document Type	Engine Type	Issue	Revision	Date	Title
SI-15-1997	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	0	2	24.11.2010	CANCELLED - Spark plugs for ROTAX engines 912/914 (Series), superseded by Maintenance Manual Line, latest edition
SI-16-1997	914 F,914 UL,912 F,912 A,912 UL	0	1	01.12.1997	Introduction of a modified oil pressure sensor 912/914
SI-17-1994	618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.06.1994	Weight, centre of gravity and moments of inertia of ROTAX UL-engines
SI-17-1997	532 UL,618 UL,582 UL,503 UL,447 UL,377 UL,277 UL	0	0	01.11.1997	Introduction of resistance spark plugs for Rotax 2-stroke engines
SI-18-1994	912 UL	1	0	01.11.1994	Grounding cable for electronic module for ROTAX 912
SI-18-1997	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	5	28.08.2006	CANCELLED - Selection of Motor Oil and General Operating Tips for Rotax engines Type 912 and 914 (series), superseded by SI-912-016/SI-914-019 latest edition
SI-19-1994	582 UL	0	0	01.06.1994	Cylinder and Piston for ROTAX 582 DCDI
SI-19-1997	618 UL	0	0	01.12.1997	Version without intake silencer 618 UL
SI-20-1994	912 UL,912 A	0	3	01.10.1996	Lubrication system for all ROTAX 912
SI-20-1997	377 UL,277 UL,914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A,618 UL,582 UL,532 UL,503 UL,447 UL	0	0	01.11.1997	New flydat configuration for Rotax UL and aircraft engines
SI-21-1994	912 ULS,912 UL,912 S,912 F,912 A	0	0	01.07.1994	CANCELLED - 912 carburetor fixation, superseded by SB-912-030/SB-914-019 (+UL), latest edition
SI-21-1997	914 F,914 UL,912 F,912 A,912 UL	0	1	01.11.1998	Introduction of the mono hook circlip at ROTAX 912 and 914 series
SI-2-1993	912 UL	0	0	01.01.1993	CANCELLED - Overload clutch for Rotax engine 912 UL, superseded by relevant Maintenance Manual, latest edition
SI-22-1994	582 UL,532 UL,618 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.12.1994	supply scope of ROTAX crankshafts
SI-22-1997	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	0	01.11.1997	Pressure oil line for hydraulic governor 912/914
SI-25-1994	912 UL	0	0	01.11.1994	Ensuring of a ground connection between screening box part no. 996 611 and engine
SI-25-1997	914 UL,912 UL,912 S,912 F,912 A,912 ULS,914 F	0	11	18.07.2007	CANCELLED - Running modifications on Rotax engine type 912 and 914 (series), superseded by SI-912-020/SI-914-022, latest edition
SI-26-1994	912 UL	0	0	01.11.1994	TBO for ROTAX engine type 912 UL-series
SI-26-1997	914 UL,912 UL	0	0	01.09.1998	Supplementing the Maintenance Manual in regard to propeller gearbox without overload clutch
SI-27-1994	912 UL	1	0	01.03.1995	Special inspection to increase the TBO for engine type 912 UL
SI-27-1997	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	1	17.07.2012	CANCELLED - Oil level check for ROTAX engine type 912 and 914 (Series), superseded by relevant Maintenance Manual, latest edition
SI-2ST-001	618 UL,582 UL	0	0	01.04.1999	Installation instructions for the new design piston for 582 UL with mono hook piston pin circlip grooves
SI-2ST-002	618 UL,582 UL	0	0	01.05.2000	Change of the exhaust gasket on engine type 582 UL mod. 90/99 und type 618 UL
SI-2ST-004	618 UL,447 UL,582 UL,503 UL	0	1	11.07.2006	Running modifications on ROTAX 2-stroke UL aircraft engines

Document Type	Engine Type	Issue	Revision	Date	Title
SI-2ST-005	582 UL	0	0	01.12.2001	Modified rotary valve cover for ROTAX engine type 582 UL (replaced by SB-2ST-002)
SI-2ST-007	618 UL,582 UL,532 UL,503 UL,447 UL	0	2	20.05.2008	Amendment on reduction gearbox type C and type E for ROTAX 2-stroke UL aircraft engines
SI-2ST-008	618 UL,582 UL,503 UL,447 UL	0	0	08.04.2009	Selection of suitable operating fluids for ROTAX 2-stroke UL engines
SI-3-1995	912 UL,912 A	0	0	01.02.1995	CANCELLED - Cracks in the carburetor flange, engine series type 912, superseded by SB-912-030/SB-914-019 (+UL), latest edition
SI-912-001,SI-914-001	912 ULS,912 UL,912 S,912 F,912 A,914 UL,914 F	0	0	01.04.1999	Installation of rotary water pump seal and water pump impeller
SI-912-002,SI-914-004	912 S,912 ULS,912 F,912 A,912 UL,914 F,914 UL	0	0	01.06.1999	Verification of the Lubrication system and replacement of the oil pressure spring for engine type 912 and 914
SI-912-003,SI-914-005	912 ULS,912 UL,912 S,912 F,912 A,914 UL,914 F	0	2	19.03.2009	Oil line connections with UNF-threads (AN-8) for ROTAX engine types 912 and 914 (series)
SI-912-004,SI-914-006	912 ULS,912 UL,912 S,912 F,912 A,914 UL,914 F	0	0	01.08.1999	CANCELLED - Modified carburetor flange for Rotax engine type 912 (series) and Rotax engine type 914 (series), superseded by SB-912-030/SB-914-019 (+UL), latest edition
SI-912-005,SI-914-007	912 ULS,912 UL,912 S,912 F,912 A,914 UL,914 F	0	0	01.02.2000	Lubrication system for all ROTAX engine type 912 (series) and 914 (series)
SI-912-006,SI-914-008	912 S,912 ULSFR,912 ULS,912 F,912 A,912 UL,914 F,914 UL	0	1	03.02.2009	Replacement of the circlip in the sprag clutch housing on ROTAX engine type 912 and 914 (series)
SI-912-007,SI-2ST-003,SI-914-009	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL,914 UL,914 F	0	0	01.08.2001	Check of the fuel pressure gauge kit part no. 874 230 for ROTAX engine type 912 and 914 (Series) and 2-stroke UL aircraft engines
SI-912-008	912 S,912 ULSFR,912 ULS,912 F,912 A,912 UL	0	1	01.02.2002	Fuel pressure indication problems on ROTAX engine type 912 (series)
SI-912-009,SI-914-010	912 S,912 ULSFR,912 ULS,912 F,912 A,912 UL,914 F,914 UL	0	0	01.10.2001	Introduction of a new rocker arm bushing for ROTAX engine type 912 and 914 (series)
SI-912-010,SI-912i-005,SI-914-011	912 ULS,912 F,912 UL,912 S,912 A,912 iS,914 UL,914 F	0	-	02.10.2012	Oil change on Rotax engine type 912i, 912 and 914 (Series)
SI-912-011,SI-914-012	912 S,912 ULSFR,912 ULS,912 F,912 A,912 UL,914 F,914 UL	0	0	01.03.2003	Replacement of the gasket rings on the adaptor of the oil radiator for Rotax engine type 912 and 914 (series)
SI-912-012,SI-914-014	912 ULS,912 UL,912 S,912 F,912 A,914 UL,914 F	0	1	01.03.2004	Routine Modifications of the Bing constant depression carburetor on ROTAX engine type 912 and 914 (Series)
SI-912-013,SI-914-016	912 ULS,912 S,912 ULSFR,912 F,912 A,912 UL,914 F,914 UL	0	0	01.04.2004	Standardization of the ignition unit for ROTAX engine type 912 and 914 (Series)
SI-912-014,SI-914-017	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,914 UL,914 F	0	0	01.06.2004	Optimizing of piston ring position for ROTAX engine type 912 and 914 (Series)
SI-912-015,SI-914-018	912 S,912 ULSFR,912 ULS,912 F,912 A,912 UL,914 F,914 UL	0	0	01.06.2004	Increase of disk spring pre-tension in the gearbox on ROTAX engine type 912 and 914 (Series)

Document Type	Engine Type	Issue	Revision	Date	Title
SI-912-016,SI-912i-001,SI-914-019	912 UL,912 S,912 F,912 A,912 ULSFR,912 ULS,912 iSc SPORT,912 iS SPORT,912 iS,914 UL,914 F	0	-	27.03.2017	Selection of suitable operating fluids for Rotax engine type 912 i, 912 and 914 (Series)
SI-912-017,SI-2ST-006	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,618 UL,582 UL,503 UL,447 UL	0	0	22.12.2006	Airfilter for Rotax engine type 912 (Series) and 2-stroke UL aircraft engines
SI-912-018,SI-912i-004,SI-914-020	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,912 iS,914 UL,914 F	0	-	02.10.2012	Purging of lubrication system for Rotax engine type 912i, 912 and 914 (Series)
SI-912-019,SI-912i-006,SI-914-021	912 ULS,912 S,912 ULSFR,912 F,912 A,912 UL,912 iSc SPORT,912 iS SPORT,912 iS,914 UL,914 F	0	-	13.06.2014	Oil leakages in the area of the cylinder barrel for Rotax engine type 912i, 912 and 914 (Series)
SI-912-020,SI-914-022	912 S,912 A,914 F,912 F,912 UL,914 UL,912 ULS	0	10	17.04.2017	Running Modifications on ROTAX Engine Type 912/914 (Series)
SI-912-021,SI-914-023,SI-2ST-009	912 F,912 A,914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,535 B,503 UL,618 UL,505 A,505,535 A,277 UL,535 C,582 UL,447 UL	0	0	09.11.2009	Inspection of carburetors for ROTAX engine type 912 and 914 (Series) and 2-stroke UL aircraft engines
SI-912-022	912 ULSFR,912 ULS,912 S,912 F,912 A,912 UL	0	0	20.01.2014	Cancelation of the 5-years change interval for fuel hoses (teflon hoses) for ROTAX Engine Type 912 (Series)
SI-912-025,SI-914-026,SI-912 i-010	912 F,914 UL,912 S,912 iSc SPORT,912 ULS,914 F,912 A,912 iS,912 UL,912 iS SPORT	0	0	30.12.2016	Change of Tightening Torque Procedure for the Installation of Cylinder Heads on ROTAX Engine Type 912 i, 912 and 914 Series
SI-912-026, SI-912 i-012	912 iS, 912 iSc SPORT, 912 iS SPORT, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	-	21.02.2017	Important notes for installing the ball bearing into the gearbox of ROTAX Engine Type 912 i, 912 and 914 (Series)
SI-912i-002	912 iSc SPORT,912 iS SPORT,912 iS	0	1	13.06.2014	B.U.D.S. Aircraft Installation Instructions for ROTAX Engine Type 912 i Series
SI-912i-003	912 iSc SPORT,912 iS SPORT,912 iS	0	4	13.06.2014	B.U.D.S. Aircraft Update for ROTAX Engine Type 912 i Series
SI-912i-007,SI-914-024,SI-912-023	912 iSc SPORT,912 iS SPORT,912 iS,914 F,912 S,912 F,912 A	0	0	04.11.2015	Introduction of a radiator retrofit kit part no. 881535 for the new radiator part no. 997083 on ROTAX engine type 912i, 912 and 914 (Series)
SI-912i-008,SI-914-025,SI-912-024	912 iSc SPORT,912 iS SPORT,912 iS,914 F,912 S,912 F,912 A	0	0	19.11.2015	Introduction of new oil radiator/-sets on ROTAX Engine Type 912 i, 912 und 914 (Series)
SI-912i-009	912 iSc SPORT,912 iS SPORT,912 iS	0	0	21.01.2016	Introduction of a new fuel filter part no. 874060 for ROTAX Engine Type 912 iS and 912 iS Sport
SI-914-002	914 F,914 UL	0	0	01.04.1999	Optimizing of mixture distribution
SI-914-003	914 UL,914 F	0	1	15.04.2008	Inspection and lubrication of Wastegate for ROTAX engine type 914 (Series)
SI-914-013	914 F,914 UL	0	0	01.04.2003	Introduction of a new airbox for Rotax engine type 914 (series)

Document Type	Engine Type	Issue	Revision	Date	Title
SI-914-015	914 F,914 UL	0	0	01.12.2003	Introduction of a new airbox part no. 667167 for Rotax engine type 914 (Series)
SL-2ST-002	447 UL,377 UL,277 UL,582 UL,535 C,535 B,535 A,532 UL,505 A,505,618 UL,503 UL,501,462 UL	0	1	12.01.2005	Documentations for ROTAX 2-stroke UL engines and certified 2-stroke aircraft engines
SL-2ST-005	503 UL,618 UL,582 UL,447 UL	0	0	01.07.2001	Running modifications on carburetors for ROTAX 2-stroke UL aircraft engines
SL-912-007	912 ULSFR	0	1	15.03.2011	ROTAX engine type 912 ULSFR - version for France
SL-912-008	912 ULS,912 UL,912 S,912 F,912 A	0	0	20.07.2000	CANCELLED - Operators and Maintenance Manual for ROTAX 912 Series - superseded by SB-2ST-000/SB-912-000/SB-914-000, current edition
SL-912-010	912 ULSFR,912 ULS,912 S	0	0	01.02.2003	Identifying abnormal vibrations on aircrafts equipped with Rotax engine type 912 S/ULS/ULSFR
SL-912-016,SL-914-014	912 A,912 F,914 F,912 ULS,912 S,914 UL,912 UL	0	1	30.12.2016	Essential information regarding engine behavior, performance and manifold pressure data for ROTAX Engine Type 912 and 914 (Series)
SL-912i-003	912 iSc SPORT,912 iS SPORT,912 iS	0	2	07.07.2016	Warranty conditions for ROTAX Engine Type 912 i Series
SL-914-001,SL-2ST-001,SL-912-001	914 UL,914 F,447 UL,377 UL,277 UL,582 UL,535 C,535 B,535 A,532 UL,508 UL,505 A,505,912 ULS,912 UL,912 S,912 F,912 A,618 UL,503 UL,501,463,462 UL	0	1	01.07.1999	Change of desig. of Tech. Bulletins and Service Information in acc. with the new ROTAX standard for ROTAX 2-stroke UL aircraft engines, ROTAX 912 (series) and ROTAX 914 (series)
SL-914-002,SL-912-002	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	2	28.05.2010	Standardization of the crankshaft/piston pin and of the gearbox for ROTAX engine type 912/914 (Series)
SL-914-003,SL-2ST-003,SL-912-003	914 UL,914 F,447 UL,377 UL,277 UL,275,185,582 UL,532 UL,535 C,535 B,535 A,912 ULS,912 UL,912 S,912 F,912 A,508 UL,505 A,505,503 UL,618 UL,501,463,462 UL	0	2	01.07.2000	CANCELLED - List of documentation for ROTAX 2-Stroke Aircraft engines and all versions of engine Type 912 / 914 - superseded by SB-2ST-000/SB-912-000/SB-914-000, current edition
SL-914-004,SL-912-004	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	2	15.04.2008	Documentation for ROTAX engine type 912 and 914 (Series)
SL-914-005,SL-912-005,SL-2ST-004	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A,377 UL,582 UL,535 C,535 B,535 A,532 UL,505 A,505,503 UL,618 UL,501,462 UL,447 UL	0	0	01.12.1999	Change of layout for: Alert Service Bulletin (ASB), Service Bulletins (SB), Service Instructions (SI) and Service Letters (SL)
SL-914-006,SL-912-006,SL-912i-006	914 UL,914 F,912 ULS,912 UL,912 S,912 iSc SPORT,912 iS SPORT,912 iS,912 F,912 A	0	-	23.07.2014	Use of third party after-market piston kits in Rotax engines type 912 (series) and 914 (series)
SL-914-007	914 UL,914 F	0	0	01.07.2000	CANCELLED - Operators and Maintenance Manual for ROTAX 914 Series - superseded by SB-2ST-000/SB-912-000/SB-914-000, current edition

Document Type	Engine Type	Issue	Revision	Date	Title
SL-914-008,SL-912-009	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	0	1	01.12.2003	CANCELLED - Coolant for ROTAX engine type 912 and 914 (Series), superseded by SB-912-043/SB-914-029, latest edition
SL-914-009,SL-912-011,SL-912i-002	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,912 iS	0	-	02.10.2012	Use of an oil thermostat for Rotax engine type 912i, 912 and 914 (Series)
SL-914-010,SL-912-012,SL-2ST-006	914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,582 UL,914 UL,503 UL,447 UL	0	3	07.07.2016	Warranty conditions for ROTAX engine types 912 and 914 (Series) and 2-stroke aircraft engines
SL-914-011,SL-912-013,SL-2ST-007	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,618 UL,582 UL,505,503 UL,463,462 UL,447 UL,377 UL	0	10	04.09.2017	List of stolen ROTAX engines type 912 and 914 (Series) and 2-stroke aircraft engines
SL-914-012,SL-912-014,SL-912i-005,SL-2ST-008	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,912 iSc SPORT,912 iS SPORT,912 iS,618 UL,535 C,503 UL,505,447 UL,505 A,535 B,277 UL,535 A,582 UL	0	-	01.09.2014	Non-approved modifications or use of ROTAX unapproved engine components or accessories for ROTAX aircraft engines
SL-914-013,SL-912-015,SL-2ST-009,SL-912i-001	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,447 UL,582 UL,912 iS,618 UL,503 UL,535 C,535 B,535 A,505,912 iSc SPORT,912 iS SPORT,505 A	0	-	08.03.2012	Definition for propeller strike or accidental engine stoppage on ROTAX engine type 912 i, 912 and 914 (Series) and 2-stroke aircraft engines
SL-914-015,SL-912-017,SL-912i-004	914 UL,912 ULS,912 UL,912 S,912 F,912 A,912 iS,914 F,912 ULSFR	0	1	07.07.2016	Conditions relating to the Limited Extended Warranty for ROTAX Engine Types 912/914 Series and 912 i Series
SL-914-016,SL-2ST-010,SL-912-018,SL-912i-007	914 UL,535 A,503 UL,912 S,535 C,277 UL,505 A,912 iS,912 F,535 B,618 UL,505,912 iS SPORT,912 A,447 UL,914 F,582 UL	0	0	08.09.2016	Language Standardization in Technical Documentation for ROTAX® Aircraft Engines